

CONVEYOR BELT REPLACEMENT

Industry:
Iron Ore

Location:
Western Australia

Staffing Requirements:
1 Project Manager,
2 Supervisors,
6 Belt Technicians

Safety Stats:
Zero Injuries

Scope of Work:
A 4300m ST2500 1800mm wide belt was lapped out before shutdown and a new belt was reinstalled during shutdown with a fox drive.

Outcomes:
Installation was completed ahead of time and under budget using a ConvaTech designed and engineered fox drive/belt winder platform. Installation was completed with a high interaction with other contractors modifying chutes on the same conveyor.

